City of Apache Junction Water Utilities Community Facilities District

District Director's Report

September 17, 2019

Chlorine Dioxide Generator Update

System is installed and operational



Well 6 / Booster 2 Generator Update

Generator and automatic transfer switch are installed





Well 5 Pump Replacement

- Field staff noticed a decline in production
 - Gallons per minute went from 400 to 310
 - AJWD requested proposals from contractors to replace the pump
 - Contractor is scheduled to pull Well 5

Well 5 Pump Replacement

- Staff will update the Board at the next meeting on the progress
- Well 5 needs to be replaced before the Central Arizona Project siphon outage in November