City of Apache Junction Water Utilities Community **Facilities District District Director's Report October 15, 2019**

Booster #1 Tank Coating Project

- Tank repairs are complete
- Sand blasting interior of the tank
- Interior coating to be applied next week
- Exterior coating on all 3 tanks will be completed by the end of the month

Booster #1 Tank Coating Project



Total Trihalomethanes 4th Quarter 2019

- Staff has seen an improvement in the water system since the install of the chlorine dioxide unit at the Superstition Area Water Plant
- The water sample was taken on October 11, 2019 and staff believes it will be below the 80 ppb based on samples taken over the past 12 weeks

Salt River Project / Apache Junction Water District Recovery Wells

- Staff is answering a request from the Arizona Department of Water Resources
- AJWD needs permission from the City of Mesa to have recovery wells in their service area

Backflow Prevention Program

Arizona Revised Statue R18-4-215 Backflow Prevention

