

City of Apache Junction Water Utilities Community Facilities District

District Director's Report

November 19, 2019

Booster #1 Tank Coating Project



Booster #1 Tank Coating Project



Well #5 Pump Replacement

- **The perforations were cleared during the cleaning process**
- **Well gravel pack entered the casing but has since been removed**
- **Pump and motor installation the week of November 18, 2019**



Total Trihalomethanes 4th Quarter 2019

- **2019 TTHM Running Annual Average**
 - 44-60 ppb
- **2018 TTHM Running Annual Average**
 - 59-86 ppb
- **2017 TTHM Running Annual Average**
 - 50-75 ppb
- **2016 TTHM Running Annual Average**
 - 57-69 ppb

Backflow Prevention Program

- **Arizona Revised Statute R18-4-215
Backflow Prevention**

